

Issue ID	Issue Type Name	Issue Category	Status	Path No	Reported Date	Resolution Date	Issue Resolution reason
61409	Defect	Drainage	UnAssigned	WG 17/16	08/04/2021		Unknown
60552	Defect	Hedges	Resolved	WG 17/1	18/02/2021	25/02/2021	No works required
60521	Defect	Hazard	Resolved	WG 17/27A	17/02/2021	17/02/2021	No works required
60505	Defect	Obstructions	Resolved	WG 17/1	15/02/2021	16/02/2021	No works required
60506	Defect	Obstructions	Resolved	WG 17/1	15/02/2021	16/02/2021	No works required
60507	Defect	Obstructions	Resolved	WG 17/1	15/02/2021	16/02/2021	No works required
59508	Improvement	Change Asset Type	Resolved	WG 17/13	27/11/2020	27/11/2020	Issue Fixed
59505	Defect	Drainage	Assigned	WG 17/24	26/11/2020		Unknown
59200	Defect	Missing	Assigned	WG 17/36	10/11/2020		Unknown
58235	Defect	Hazard	Resolved	WG 17/8	02/09/2020	11/09/2020	Issue Fixed
58191	Defect	Overgrowth	Resolved	WG 17/24	31/08/2020	01/09/2020	No works required
58192	Defect	Obstructions	Resolved	WG 17/24	31/08/2020	06/11/2020	Issue Fixed
58190	Defect	Obstructions	Assigned	WG 14/6	31/08/2020		Unknown
58020	Defect	Defect	Resolved	WG 17/25	19/08/2020	24/08/2020	Issue Fixed
56825	Defect	Missing	Resolved	WG 17/22	10/06/2020	10/06/2020	Asset Replaced
56255	Defect	Overgrowth	Resolved	WG 17/17	12/05/2020	24/07/2020	No works required
56256	Defect	Obstructions	Assigned	WG 17/17	12/05/2020		Unknown
56100	Defect	Overgrowth	Resolved	WG 17/30	05/05/2020	22/05/2020	Issue Fixed
55817	Defect	Obstructions	Assigned	WG 17/17	20/04/2020		Unknown
54890	Defect	Vehicle Use	Resolved	WG 17/23	06/02/2020	23/10/2020	Issue Fixed
54446	Defect	Missing	Assigned	WG 14/6	18/12/2019		Unknown
53822	Defect	Obstructions	Assigned	WG 17/17	15/10/2019		Unknown
52822	Defect	Overgrowth	Assigned	WG 17/5	26/07/2019		Unknown
50671	Defect	Defect	Assigned	WG 17/24	25/01/2019		Unknown
46179	Defect	Hazard	Assigned	WG 17/34	26/10/2017		Unknown
30561	Defect	Other	Assigned	WG 17/36	24/03/2015		Unknown
26557	Defect	Defect	Assigned	WG 17/12	25/02/2014		Unknown
5723	Defect	Obstructions	Assigned	WG 14/6	10/04/2008		Unknown



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL1220040463000 Schedule: L1000

Policy / Contract Name: WELLINGTON TOWN COUNCIL

Name of Occupier: WELLINGTON TOWN COUNCIL

Address: WARDLEWORTH HOUSE TONEDALE WELLINGTON TA21 0AA

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
99	General Play Area	Playing Field	
64951269/41	(a) None. (b) None.	It is recommended that signage is fitted displaying the following information: Owner's name address and telephone number. Location of the nearest telephone Location of the nearest First Aid Kit Location of the nearest Public Toilets Age Restrictions Prohibition of Dogs Prohibition of Wheeled Play Equipment.	11/01/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Philip Turner
Designation: Engineer Surveyor

Contact: philip.turner@uk.zurich.com
Telephone: 07875 887583

Date: 11/01/2021



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL1220040463000 Schedule: L1000

Policy / Contract Name: WELLINGTON TOWN COUNCIL

Name of Occupier: WELLINGTON TOWN COUNCIL

Address: WARDLEWORTH HOUSE TONEDALE WELLINGTON TA21 0AA

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
06	Infant Carousel Wicksteed	Playing Field	Wicksteed
110701269/34	(a) None. (b) None.	None.	11/01/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Philip Turner
Designation: Engineer Surveyor

Contact: philip.turner@uk.zurich.com
Telephone: 07875 887583

Date: 11/01/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL1220040463000 Schedule: L1000

Policy / Contract Name: WELLINGTON TOWN COUNCIL

Name of Occupier: WELLINGTON TOWN COUNCIL

Address: WARDLEWORTH HOUSE TONEDALE WELLINGTON TA21 0AA

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
01	Set of Four Swings Two flat, two cradle. Hirst	Playing Field	Hirst
940368203/45	(a) None. (b) None.	Cradle swings removed	11/01/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Philip Turner
Designation: Engineer Surveyor

Contact: philip.turner@uk.zurich.com
Telephone: 07875 887583

Date: 11/01/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL1220040463000 Schedule: L1000

Policy / Contract Name: WELLINGTON TOWN COUNCIL

Name of Occupier: WELLINGTON TOWN COUNCIL

Address: WARDLEWORTH HOUSE TONEDALE WELLINGTON TA21 0AA

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
02	Slide Hirst	Playing Field	Hirst
940378203/45	(a) None. (b) None.	None.	11/01/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Philip Turner
Designation: Engineer Surveyor

Contact: philip.turner@uk.zurich.com
Telephone: 07875 887583

Date: 11/01/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL1220040463000 Schedule: L1000

Policy / Contract Name: WELLINGTON TOWN COUNCIL

Name of Occupier: WELLINGTON TOWN COUNCIL

Address: WARDLEWORTH HOUSE TONEDALE WELLINGTON TA21 0AA

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
03	Horizontal Ladder	Playing Field	
940388203/45	(a) None. (b) None.	None.	11/01/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Philip Turner
Designation: Engineer Surveyor

Contact: philip.turner@uk.zurich.com
Telephone: 07875 887583

Date: 11/01/2021

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 456 1311 Fax: 0121 697 9136 Email: engineering@uk.zurich.com

Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.



REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: YLL1220040463000 Schedule: L1000

Policy / Contract Name: WELLINGTON TOWN COUNCIL

Name of Occupier: WELLINGTON TOWN COUNCIL

Address: WARDLEWORTH HOUSE TONEDALE WELLINGTON TA21 0AA

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
07	Multi Use Games Area GB Sports & Leisure	Playing Field	GB Sports & Leisure
30331283/28	(a) None. (b) None.	None.	11/01/2021

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations.

Authenticated by: Philip Turner
Designation: Engineer Surveyor

Contact: philip.turner@uk.zurich.com
Telephone: 07875 887583

Date: 11/01/2021

info@wellingtontowncouncil.co.uk

From: [REDACTED]
Sent: 07 April 2021 16:30
To: info@wellingtontowncouncil.co.uk
Subject: Dog poo bin URGENT

Flag Status: Flagged

Good evening I am writing to you again as a matter of urgency. Myself and many many other dog walkers in the area of Kates farm are desperate for dog poo bin to the opening of the field by Aspin close small playpark where people climb over the hedge. It has become worse and worse-walkers just dumping their bags near the entrance and something has got to be done! I absolutely appreciate there is a cost involved but I believe this is necessity. if I had to do a petition I can guarantee I would get several hundred names on it we have mentioned it so many times and mentioned it to local offices and so forth. I am a resident on Aspin Close and an absolutely sick of finding ditched bags, or worse just the poo left due to laziness. Please please PLEASE can we get a bin here?!!!

Kind regards

Mrs Barsby
[REDACTED]

AGENDA ITEM 11C

Author: A. Kendall

Date: 08/04/2021

